

SEP 10 1982

1. COUNTY Crawford CHECK (✓) ONE: Town Village City Name Seneca

2. LOCATION SE of SE NE, SE Section 10 Township 10N Range 6W 3. NAME OWNER AGENT AT TIME OF DRILLING CHECK (✓) ONE
OR - Grid or Street No. Street or Road Name ADDRESS Roy Schill
1116 N. 10th Ave

AND - If available subdivision name, lot & block No. POST OFFICE Onalaska ZIP CODE WI 54650
North West part

4. Distance in feet from well to nearest: (Record answer in appropriate block) Building 20' Sanitary Bldg. Drain C.I. Other Sanitary Bldg. Sewer C.I. Other Floor Drain Connected To: C.I. Sewer Other Sewer Storm Bldg. Drain C.I. Other Storm Bldg. Sewer C.I. Other

Street Sewer San. Storm Other Sewers C.I. Other Foundation Drain Connected to: Sewer Sewage Sump Clearwater Dr. Sewage Sump Clearwater Sump Sewage Sump C.I. Other Clearwater Sump Clearwater Sump Sewage Sump Holding Tank Septic Tank Sewage Absorption Unit Seepage Pit Seepage Bed Seepage Trench 100' Manure Hopper or Retention or Pneumatic Tank

Privy Pet Waste Pit Pit: Nonconforming Existing Well Pump Tank Subsurface Pumproom Nonconforming Existing Barn Gutter Animal Barn Pen Animal Yard Silo With Pit Glass Lined Storage Facility Silo w/o Pit Earthen Silage Storage Trench Or Pit Earthen Manure Basin

Temporary Manure Stack or Platform Watertight Liquid Manure Tank or Basin Manure Pressure Pipe Subsurface Gasoline or Oil Tank Waste Pond or Land Disposal Unit (Specify Type) Manure Storage Basin Concrete Floor Only Concrete Floor and Partial Concrete Walls Other (Describe)

5. Well is intended to supply water for: Country home

6. DRILLHOLE

Dia. (in.)	From (ft.)	To (ft.)	Dia. (in.)	From (ft.)	To (ft.)
<u>10</u>	<u>0</u> Surface	<u>126</u>	<u>6</u>	<u>126</u>	<u>530</u>

7. CASING, LINER, CURBING AND SCREEN

Dia. (in.)	Mfg. & Method of Assembly	From (ft.)	To (ft.)
<u>6</u>	<u>new black steel A-53 Valley steel Pithus adaptor</u>	<u>0</u> Surface	<u>126</u>

8. GROUT OR OTHER SEALING MATERIAL

Kind	From (ft.)	To (ft.)
<u>clay</u>	<u>0</u> Surface	<u>8</u>
<u>cement</u>	<u>8</u>	<u>126</u>

9. FORMATIONS

Kind	From (ft.)	To (ft.)
<u>clay</u>	<u>0</u> Surface	<u>40</u>
<u>lime rock</u>	<u>40</u>	<u>210</u>
<u>sand rock</u>	<u>210</u>	<u>290</u>
<u>shale stone</u>	<u>290</u>	<u>510</u>
<u>sand rock</u>	<u>510</u>	<u>530</u>

10. TYPE OF DRILLING MACHINE USED

Cable Tool Rotary-hammer w/drilling mud & air Jetting with

Rotary-air w/drilling mud Rotary-hammer & air Air

Rotary-w/drilling mud Reverse Rotary Water

Well construction completed on 7-9 19 82

11. MISCELLANEOUS DATA

Yield Test: 3 Hrs. at 8 GPM Well is terminated 12 inches above final grade below

Depth from surface to normal water level 475 Ft. Well disinfected upon completion Yes No

Depth of water level when pumping 478 Ft. Stabilized Yes No Well sealed watertight upon completion Yes No

Water sample sent to Madison laboratory on 8-2 19 82

Your opinion concerning other pollution hazards, information concerning difficulties encountered, and data relating to nearby wells, screens, seals, method of finishing the well, amount of cement used in grouting, blasting, etc., should be given on reverse side.

Signature 186 Donald C. Kirschbauer Registered Well Driller Business Name and Complete Mailing Address Rt 4 Box 75 Done Well Drilling Escobal WI 53805