WELL CONSTRUCTOR'S REPORT TO WISCONSIN STATE BOARD OF HEALTH See Instructions on Reverse Side	
~ // *	
1. County	Village A Gustulle.
2. Location 300 18 18 18 18 18 18 18 18 18 18 18 18 18	(City hack one and give name
2. Location (2008 / 3. L. F. 7.	Chlow (Sec 14023)
3. Owner Dor Agent	
4. Mail Address	
5. From well to nearest: Buildingft; sewerft; drainft; septic tank_ff;	
5. From well to nearest: Buildingft; sewer	ft; drainft; septic tanki_Q_ft;
dry well or filter bedft; abandoned wellft.	
6. Well is intended to supply water for: Jan Station	
7. DRILLHOLE:	10. FORMATIONS:
Dia. (in.) From (ft.) To (ft.) Dia. (in.) From (ft.) To (ft.)	! From ! To
114 + 111 + B+	Kind (ft.) (ft.)
7 /of 1/0 4 /ox	Sand + groves top 105
8. CASING AND LINER PIPE OR CURBING:	Dan Mircha 105/10
Dia. (in.) Kind and Weight From (ft.) To (ft.)	
4 1/ H Steel 165	RECE
	AUG 21 1960
1	
9. GROUT:	CNITARY
Kind From (ft.) To (ft.)	ENGINEE
None	
	Construction of the well was completed on:
11. MISCELLANEOUS DATA:	1960
Yield test: 3 GPM.	The well is terminatedinches
Depth from surface to water-level:ft.	above , below □ the permanent ground surface.
· • !	Was the well disinfected upon completion?
Water-level when pumping:ft.	Yes No
Water sample was sent to the state laboratory at:	Yes No
" .	Was the well sealed watertight upon completion?
Madri on 1960	Yes No
<u> </u>	
Signature Educin D Mly	New alli Dowa
Registered Well Driller	Complete Mail Address
Please do not write in space below	
28781	10 ml 10 ml 10 ml 10 ml
Rec'dNoNoNo	
Ans'dUNSAFE	Gas24 hrs
Interpretation	48 hrs
Because of the presence of B. Coli in	Continu
one of the 10 cc. portions of this sam-	Confirm
ple another examination is advisable.	B. Coli 1
	Examiner
,	

801