WELL LOG *and* REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.

5 ft Wt. Pipe
well drillers
Special

F.S. Shoe

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

Inches Diameter
2 3 4 5 6 8 10 12 14 16 18



Draw the diagram to show the right half only

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Clay

Sand & gravel

Sand Rock.

Record of FINAL Pumping test

Duration of test
Hours 4

Pumping rate
G.P.M. ----------

Depth of pump in well. Ft. 63 ft.

Standing water-level (from surface)
Ft. 60 ft.

Water-level when pumping Ft. ----------

Water. End of test.
Clear Clear
Cloudy ----------
Turbid ----------

Was the well sterilized?
Yes Yes No ----------

To which laboratory was sample sent?
Madison
Date 9-3-43

Was the well sealed on completion?
Yes X No ----------

How high did you leave the casing-pipe above grade?
3 ft

Well was completed
Date 8-25-1943

Well Driller
Carl Williams
Signature

247-2