

WELL LOG and REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of FINAL Pumping test

Rebaric 70' Drilled 92 feet into Sand Rock

Inches Diameter	Depth
2 3 4 5 6 8 10 12 14 16 18	
	25
	50
	75
	100
	150
	200
	289
	379
	400
	800
	1200

Duration of test
Hours 11 hours

Pumping rate
G.P.M. 12 P.M.

Depth of pump in well. Ft. 369

Standing water-level (from surface)
Ft. 314'

Water-level when pumping Ft. 314

Water. End of test.
Clear
Cloudy _____
Turbid _____

Was the well sterilized?
Yes No _____

To which laboratory was sample sent?

Date _____

Was the well sealed on completion?
Yes _____ No _____

How high did you leave the casing-pipe above grade?

Well was completed
Date 11/28 39

Well Driller
Eugene Miller
Signature

Depth
Top of well at starting point
↑

379
↑
Dep when completed
379.

← 5"

Draw the diagram to show the right half only