WELL LOG and REPORT

	···		······································	
In this column indicate the kind of casing, liner, shoe and other accessories used.	WELL DIAGRAM Use a red line to show casing or liner pipe. Use black for drill or borehole.		In this column state the kind of formations penetrated, their thickness in feet and if water bearing.	Record of FINAL Pumping test
Std. W. pipe Well Amillers	Inches Diameter 2 3 4 5 6 8 10 12 14 16 18	Depth	blay + gravel	Duration of test Hours
"Special"		25	15.71	Pumping rate G.P.M.
Dement.			Broken Limestone * mud preketo	Depth of pump in
F3 thre		50	shite Sand wek 30 H	1 7011
	7271		30 ft	(from-surface) Ft
		75		Water-level when pumping Ft.
	·	100		Water. End of test. Clear Cloudy
		:		Turbid
		150		Yes No
		200	: :	To which laboratory was sample sent? Date
				Was the well sealed or completion?
		400		YesNo
				How high did you leave the casing-pipe above grade?
		800		Well was completed Date
	Draw the diagram to show right half only	1200 v the		Well Driller Signature