

# WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39.

In this column indicate the kind of casing, liner, shoe and other accessories used.

**WELL DIAGRAM**  
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of **FINAL** Pumping test

*6 1/2' Galv. Casing*

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
		25
		50
		75
		80
		100
		150
		174
		200
		265
		400
		800
		1200

*80' Clay*

*94' Broken Rock*

*9' white Sand Rock*

Duration of test  
Hours *4 hrs*

Pumping rate  
G.P.M. *7*

Depth of pump in well. Ft. *25-8*

Standing water-level (from surface)  
Ft. *231*

Water-level when pumping Ft. *231*

Water. End of test.  
Clear   
Cloudy   
Turbid

Was the well sterilized?  
Yes  No

To which laboratory was sample sent?  
*Madison*  
Date *9-12-1942*

Was the well sealed on completion?  
Yes  No

How high did you leave the casing-pipe above grade?  
*14 inches*

Well was completed  
Date *Aug - 1942*

Well Constructor  
*Carl Williams*  
Signature

Draw the diagram to show the right half only