## WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39.

In this column indicate the kind of casing, liner, shoe and other accessories used.	WELL DIAGRAM Use a red line to show casing or liner pipe. Use black for drill or borehole.	In this column state the kind of formations penetrated, their thickness in feet and if water bearing.	Record of FINAL Pumping test
	Inches Diameter 2 3 4 5 6 8 10 12 14 16 18 Depth	clay 1	Duration of test Hours
galv Casing	3 4		Pumping rate G.P.M.  Depth of pump in well. Ft. 344
Casing	50	Broken Imestone & mud pocketos	Standing water-level
	75	64	Water-level when 3/4 pumping Ft 3/4
·	100	Solid Ime Stone	Water. End of test. Clear Cloudy Turbid
	150	Stone 135	Was the well sterilized? YesNo
	200	Blue Skale	To which laboratory was sample sent?  Date 9-12-47
	35	Sand Stone	Was the well sealed on comple- tion? YesNo
	800		How high did you leave the casing-pipe above grade?
			Well was completed  Date 5 - 1942
CR 1119-2	Draw the diagram to show the right half only	<b>-</b> i	Well Constructor William Signature