WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-1939.

In this column indicate the kind of casing, liner, shoe and other accessories used.	WELL DIAGRAM Use a red line to show casi or liner pipe. Use black i drill or borehole.	In this column state the kind of formations penetrated, their thickness in feet and if water bearing.	Record of FINAL Pumping test
Lahr. Stand.	Inches Diameter 2 3 4 5 8 8 10 12 14 16 18	Shale 5 of water bearing	Duration of test
Solv. Stand. Ripe 55 ft. Forged Steel		watter bearing 40 ft	Pumping rate G.P.M
pol			Depth of pump in well. Ft. 54
M. Rump flange		50 Gasing	Standing water-level (from surface) Ft. 440
Force pump		77 1	Water-level when pumping Ft3.7
		00	Water. End of test. Clear
		50	Turbid Was the well sterilized? Yes No
			To which laboratory we sample sent? Wie State Board
		300	Was the well sealed completion?
		.00	Yes No
	1	00	Well was completed
			Date Supt 40
	Draw the diagram totehow the right half only	200	Well Driller Howard Grun you Signature

1133-2