

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of
FINAL
Pumping test

	Inches Diameter										Depth
	2	3	4	5	6	8	10	12	14	16	
<i>galv. Casing</i>											25
											50
											75
											100
											150
87'											200
										400	
										800	
										1200	

Freestone

*white sand
Rock*

*Blue shale
5'*

Duration of test
Hours..... 4

Pumping rate
G.P.M.....

Depth of pump in well. Ft..... 95

Standing water-level (from surface)
Ft..... 95

Water-level when pumping Ft.....

Water. End of test.
Clear.....
Cloudy.....
Turbid.....

Was the well sterilized?
Yes No.....

To which laboratory was sample sent? Madison
Date 7-17-43

Was the well sealed on completion?
Yes..... No

How high did you leave the casing-pipe above grade?
12 in.

Well was completed
Date 7-10-1943

Well Constructor
Carl Williams
Signature

Draw the diagram to show the right half only