

# WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39. Accuracy is essential.

In this column indicate the kind of casing, liner, shoe and other accessories used.

**WELL DIAGRAM**  
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of FINAL Pumping test

Inches Diameter	Depth
2 3 4 5 6 8 10 12 14 16	
	25
	50
	75
	100
	150
	200
	400
	800
	1200

*Steel Drive Pipe*

*Mud & gravel*

*Solid white Sand Rock*

Duration of test  
Hours *4 hr*

Pumping rate  
G.P.M. \_\_\_\_\_

Depth of pump in well. Ft. *105 ft*

Standing water-level (from surface)  
Ft. *40 ft*

Water-level when pumping Ft. \_\_\_\_\_

Water. End of test.  
Clear \_\_\_\_\_  
Cloudy \_\_\_\_\_  
Turbid \_\_\_\_\_

Was the well sterilized?  
Yes  No \_\_\_\_\_

To which laboratory was sample sent?  
*Madison*

Date *1946*

Was the well sealed on completion?  
Yes  No \_\_\_\_\_

How high did you leave the casing-pipe above grade?  
*3 ft*

Well was completed  
Date *5-20-1946*

Draw the diagram to show the full diameter and right section of well only.

Well Constructor  
*Carl Hallin*  
Signature