This was a Recasing job. Pulled out the old gal. casing (40), rimmed down a 10" hole to 54, and Grouted it in.