

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39. Accuracy is essential.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of FINAL Pumping test

39'
BLK SEAM
STEEL
CASING

Inches Diameter
2 3 4 5 6 8 10 12 14 16

Depth

Inches Diameter										Depth
2	3	4	5	6	8	10	12	14	16	
										25
										50
										75
										100
										150
										200
										400
										800
										1200

15' Mud.

15' mud + H₂O

lime to ROCK.

lime Rock

SAND ROCK.

156' DEEP

See letter 11-4-44

Duration of test, Hours 8 hrs

Pumping rate G.P.M. 8

Depth of pump in well. Ft. 144'

Standing water-level (from surface) Ft. 30

Water-level when pumping Ft. about SAME

Water. End of test. Clear CLEAR

Cloudy _____
Turbid _____

Was the well sterilized? Yes YES No _____

To which laboratory was sample sent?
OWNER TO SEND
Date SAMPLE WHEN C. PUMP IS INSTALLED

Was the well sealed on completion? Yes YES No _____

How high did you leave the casing-pipe above grade? 14 inches

Well was completed Date Aug 3, 1944

Well Constructor H. W. BARTELS
Signature

Draw the diagram to show the full diameter and right section of well only.