## WELL CONSTRUCTOR'S REPORT TO WISCONSIN STATE BOARD OF HEALTH See Instructions on Reverse Side

1. County Chauford	Town Bridge Sort
2 Toursian 7 1 # 19 - 15 /m by 1	City Check one and give name  Section, Town and Range numbers
3. Owner $\square$ or Agent $\square$ . Study leke $\square$ .	
4. Mail Address Trairie Complete add	wind, wis RJ. D#2.
5. From well to nearest: Building 5ft; sewerft; drainft; septic tankft;	
dry well or filter bedft; abandoned wellftft.	
6. Well is intended to supply water for:	
7. DRILLHOLE:	10. FORMATIONS:
Dia. (in.) From (ft.) To (ft.) Dia. (in.) From (ft.) To (ft.)	Kind From To (ft.)
10" 0 4	Job sail Least 0 5
5" 4 158	Sand loose Lord 5 14
8. CASING AND LINER PIPE OR CURBING:	Gravel-Some Morole 14 25
Dla. (in.) Kind and Weight From (ft.) To (ft.)	30 25 15 R
5" Stan Steel	Jan 153 158
Blakike 43 Husel.	
	RECEIVED
9. GROUT:	AUG 1 5 1857
Kind From (ft.) To (ft.)	
	SANTATION
	Construction of the well was completed on:
11. MISCELLANEOUS DATA:	May 31 1956
	The well is terminatedinches
Yield test:12 Hrs. at GPM.	The well is terminated inches $\$ above, below $\square$ the permanent ground surface.
Depth from surface to water-level: 25 ft.	
Water-level when pumping: Same ft.	Was the well disinfected upon completion?
li i i i i i i i i i i i i i i i i i i	Yes No
Water sample was sent to the state laboratory at:	Was the well sealed watertight upon completion?
Madison on June 18 1959	Yes_ <i>Jes_</i>
71 (1) 1) - 40 1) 0(1)	) 10-0 - 0 1111
Signature N.W. Barles P.O.T. Registered Well Driller	Complete Mail Address
Please do not wri	
Rec'd No	10 ml 10 ml 10 ml 10 ml
Ang'd	Gas-24 hrs
Interpretation	48 hrs
	Confirm
·	B. Coli
	Evaminer