

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of FINAL Pumping test

5" std. wt. steel pipe - 35'

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
		25
		36
		44
		50
		75
		100
		150
		200
		400
		800
		1200

Clay + Shale 10'

Limestone

See letter re: non conformance 12-9-41

Duration of test Hours 3-4

Pumping rate G.P.M. 10

Depth of pump in well. Ft. 42

Standing water-level (from surface) Ft. 10

Water-level when pumping Ft. 16

Water. End of test.
Clear
Cloudy _____
Turbid _____

Was the well sterilized?
Yes _____ No

To which laboratory was sample sent?
Madison
Date 11/28

Was the well sealed on completion?
Yes No _____

How high did you leave the casing-pipe above grade?
6"

Well was completed Date 11/23/41

Well Constructor Joe Ball
Signature

Draw the diagram to show the right half only

326-R