

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39. Accuracy is essential.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of FINAL Pumping test

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16	2 3 4 5 6 8 10 12 14 16	
		25
		50
		75
		100
		150
		200
		400
		800
		1200

49' Star Steel casing

94 ft deep

CLAY.

SHALE

AND

ROCK.

Duration of test
Hours 10 hrs

Pumping rate
G.P.M. 8 gals

Depth of pump in well. Ft. 80 feet

Standing water-level (from surface)
Ft. 34 ft

Water-level when pumping Ft. Same

Water. End of test.
Clear Clear
Cloudy _____
Turbid _____

Was the well sterilized?
Yes Yes No _____

To which laboratory was sample sent?
Madison Wis.
Date July 12, 1943

Was the well sealed on completion?
Yes Yes No _____

How high did you leave the casing-pipe above grade?
15 in

Well was completed
Date April 23, 1943
Perforated July 5th
Well Constructor
H. W. Bartels
Signature

Draw the diagram to show the full diameter and right section of well only.