Mr. Lewis Harris November 6, 1968 Page 2

Kindly enter the above requested information on the construction report for the Rod Satter well and return the report to this office at an early date.

Very truly yours,

DIV. OF ENVIRONMENTAL PROTECTION

Charles W. Souther

Charles W. Goethel Private Water Supply Section

CWG:ps cc: Region 1 Enc.

Vais is an near as I would tell at formations as when riming the culting go down a head and as I stirred them up to Clean them out it is hard to tell which is which after I went through the Brown Time the rest of the rock was real hard all the way to the sand and the rock below shall was wal hard. The outy reason that I put in that much 6" Casing was because He wanted to Put in a subjump and there was about 15H- & Sand and Shalo in Bottom of the well went I started to Drillit Deeper and if the keept falling in Hes Pump would last long and don't what your Think about 4th liners but I don't