WELL LOG and REPORT

	1	4	1
In this column indicate the kind of casing, liner, shoe and other accessories used.	WELL DIAGRAM Use a red line to show casing or liner pipe. Use black for drill or borehole.	In this column state the kind of formations penetrated, their thickness in feet and if water bearing.	Record of FINAL Pumping test
	Inches Diameter Dept. 2 3 4 5 6 8 10 12 14 16 18	hi	
		CIAU	Hours Stest & Russ
27' Stan Steel HEAVY CASING	25	i 6	Pumping rate G.P.M. 6 gala:
		1	Depth of pump in well. Ft. 3-24
	50	, W E	Standing water-level (from surface) Ft. 280
	75	\$ ⁺	Water-level when pumping Ft. Same
DEPTH OF WEIL	100	. E	Water. End of test. Clear Cloudy
	150		Turbid Was the well sterilized? Yes No
	200	95 FEET SAND BOCK.	To which laboratory was sample sent? Madiaan) Wia Date 7-16-41-630P
	400		Was the well sealed on completion? Yes
			How high did you leave the casing-pipe above grade?
	800		Well was completed Date 7-18-41
597-2	Draw the diagram to show the right half only		Well Driller N. W. Battelo. Signature