

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of FINAL Pumping test

62 ft of heavy Gas pipe casing

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
-----		25
-----		50
-----		74 75
-----		100
-----		150
-----		200
-----		400
-----		800
-----		1200

This is a steel well

clay
20 ft
mud
60 ft
62
Rock sand layers

Cementing not done due to weather

Duration of test
Hours *hours*

Pumping rate
G.P.M. *5*

Depth of pump in well. Ft. *48 ft*

Standing water-level (from surface)
Ft. *26*

Water-level when pumping Ft. *Unknown*

Water. End of test.
Clear _____
Cloudy _____
Turbid _____

Was the well sterilized?
Yes _____ No _____

To which laboratory was sample sent?

Date _____

Was the well sealed on completion?
Yes _____ No _____

Pump fastened to casing

How high did you leave the casing-pipe above grade?

Well was completed
Date *Dec 20*

Well Constructor
Joe Wolf
Signature

622-R

Draw the diagram to show the right half only