WELL CONSTRUCTOR'S REPORT TO WISCONSIN STATE BOARD OF HEALTH See Instructions on Reverse Side

1. County Crass ford	Village Eastman
2. Location 8 miles NW of a	City Check one and give name Compared to the
3. Owner or Agent Designational	Mall
4. Mail Address Eastman	P. 7. D. His
5. From well to nearest: Building 19 ft; sewer 50 ft; drain 50 ft; septic tank 75 ft;	
dry well or filter bed / Q_O_ft; abandoned well 2	Looft.
6. Well is intended to supply water for:	m + home
7. DRILLHOLE:	10. FORMATIONS:
Dia. (in.) From (ft.) To (ft.) Dia. (in.) From (ft.) To (ft.)	Kind EN CONTENTAL
7 0 5/9 5 5/9 530	Clay + loose 20
	Listianos 20 240
8. CASING AND LINER PIPE OR CURBING:	Rand Tome 240 320
Dia. (in.) Kind and Weight From (ft.) To (ft.)	00 370 370
5 standard 0 519	00 10 10 370 4 3 A
	Train each Trac
	Randskones 420 7-10
	Flowing Rand 470 510
9. GROUT: Kind From (ft.) To (ft.)	sandatore 5/0 330
- 1/7-	
Clay 5/0	Construction of the well was completed on:
20000 Rana 4/0010	2h 2 / 57
11. MISCELLANEOUS DATA:	1950
Yield test: GPM.	The well is terminated inches
Depth from surface to water-level: 500 ft.	📥 above, below 🔲 the permanent ground surface.
	Was the well disinfected upon completion?
Water-level when pumping:ft.	Yes No
Water sample was sent to the state laboratory at:	
Madison on June 23 1958	Was the well sealed watertight upon completion?
City	YesNo
Signature Alexand Well Driller Registered Well Driller Please do not wr	P3 Box 36 Box colo Mis. Complete Mail Address
Rec'd JUN 24 1958 No.18185	10 ml 10 ml 10 ml 10 ml
Ans'd	Gas-24 hrs
InterpretationCA	48 hrs
JAFE	
	Confirm
	B. Coli
	Examiner

625