WELL CONSTRUCTOR'S REPORT TO WISCONSIN STATE BOARD OF HEALTH See Instructions on Reverse Side

A 1	(Town []
1. County Daward	Village & Eastman Win
2. Location 2. 12 Total	City Check one and give name (80)
Name of street and number of premise	or Section. Town and Range numbers
3. Owner For Agent	partnership or firm
4. Mail Address <u>Complete add</u>	ress required
5. From well to nearest: Building_ $Z_{}$ ft; sewer	ft; drain/Soft; septic tank/Soft;
dry well or filter bed 200_ft; abandoned well_1	RECEIVED
6. Well is intended to supply water for:	me and Stock MAY 18 1959
7. DRILLHOLE:	10 FORMATIONS.
Dis. (in.) From (ft.) To (ft.) Dis. (in.) From (ft.) To (ft.)	ENYLRONMENTAL SANITATION
10 0 44/2 6 44/2 420	Aufara 0 5
	Clare and Boulder 5 12
8. CASING AND LINER PIPE OR CURBING:	Platrille 12 100
Dia. (in.) Kind and Weight From (ft.) To (ft.)	th. lime 100 115
6 Black Pine 0 444	Oil Rock 115 122/2
	Glass Rock 1224/25
	Trenton 125 / 55
9. GROUT:	St. Peters Land 165 210
Kind From (ft.) To (ft.)	Prairie Dn Chin 210 420
next Cement 7 444	
	Construction of the well was completed on:
11. MISCELLANEOUS DATA:	april 27 1959
Yield test: Hrs. at GPM.	The well is terminated inches
Depth from surface to water-level: 370 ft.	🔀 above, below 🗌 the permanent ground surface.
_	Was the well disinfected upon completion?
Water-level when pumping: _3_95ft.	Yes No
Water sample was sent to the state laboratory at:	Was the well sealed watertight upon completion?
on 19	YesNo
City	168_121 NU
Signature Tory Registered Well Driller Please do not write	Complete Mail Address
Rec'd MAY 6 1959 1,1265	10 ml 10 ml 10 ml 10 ml
	Gas-24 hrs
Interpretation	48 hrs.
interpretation	
· ·	Confirm
	B. Coli
	Examiner

636