

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of FINAL Pumping test

32ft of 4 inch standard pipe
1 shoe.

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
		25
		32
		42
		50
		75
		100
		150
		200
		400
		800
		1200

20 ft. of top soil.

22 ft of Blue shale

Depth of well.

Duration of test

Hours 4 hrs.

Pumping rate

G.P.M. 5 gal.

Depth of pump in well.

Ft. 40

Standing water-level (from surface)

Ft. 22

Water-level when pumping

Ft. 22

Water. End of test.

Clear

Cloudy

Turbid

Was the well sterilized?

Yes No

To which laboratory was sample sent?

Slate

Date 10/15/43

Was the well sealed on completion?

Yes No

How high did you leave the casing-pipe above grade?

1 ft.

Well was completed

Date Oct 1, 1943

Well Constructor

E. S. Waters
Signature

Draw the diagram to show the right half only.

675-2