

WELL LOG and REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of FINAL Pumping test

5 inch standard
Pipe Drive shoe
Duplex Pump stand

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
		25
		50
		60
		74 75
		100
		150
		200
		400
		800
		1200

15 ft surface clay.

30 ft gravel.

29 ft white sand
rock.

Duration of test
Hours 4 hours

Pumping rate
G.P.M. 25

Depth of pump in well. Ft. Pressure system

Standing water-level (from surface)
Ft. 12 ft.

Water-level when pumping Ft. 12 ft.

Water. End of test.
Clear
Cloudy
Turbid

Was the well sterilized?
Yes No

To which laboratory was sample sent?
state

Date 31 june

Was the well sealed on completion?
Yes No

How high did you leave the casing-pipe above grade?
1 ft.

Well was completed
Date Jan 10, 1940

Well Driller
E. S. Water
Signature

Draw the diagram to show the right half only

694-2