

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39. Accuracy is essential.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of
FINAL
Pumping test

Duplex Pump stand standard 34 ft of pipe in casing.

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16		
		25
		34
		40
		50
		75
		100
		113
		150
		200
		400
		800
		1200

30 ft of top

Soil

83 ft of lime rock and Flint rock.

depth

Duration of test
Hours *2 hrs*

Pumping rate
G.P.M. *5 gal.*

Depth of pump in well. Ft. *112*

Standing water-level (from surface)
Ft. *97 ft.*

Water-level when pumping Ft. *Weak vein. Pumps dry.*

Water. End of test.
Clear

Cloudy _____
Turbid _____

Was the well sterilized?
Yes No _____

To which laboratory was sample sent?
state
Date *Sept. 20 1943*

Was the well sealed on completion?
Yes No _____

How high did you leave the casing-pipe above grade?
1 ft.

Well was completed
Date *29 Aug 43*

Well Constructor
E. S. Waters
Signature

Draw the diagram to show the full diameter and right section of well only.