

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-1939.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of **FINAL** Pumping test

*six in standard Pipe
Portland Cement
Duplex Pump stand*

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
		25
		32 ft
		50
		75
		96 ft deep
		100
		150
		200
		400
		800
		1200

24 ft top soil

Balance Lime Rock.

Duration of test
Hours *3 hrs*

Pumping rate
G.P.M. *5 1/2 min*

Depth of pump in well. Ft. *93 ft*

Standing water-level (from surface)
Ft. *80 ft*

Water-level when pumping Ft. *80 ft*

Water. End of test.
Clear *clear*
Cloudy _____
Turbid _____

Was the well sterilized?
Yes No _____

To which laboratory was sample sent?
State
Date *Aug 25*

Was the well sealed on completion?
Yes No _____

How high did you leave the casing-pipe above grade?
1 ft

Well was completed
Date *Aug 15 - 1941*

Well Driller
E. S. Quater
Signature

Draw the diagram to show the right half only