WELL LOG and REPORT

For method of making report, refer to builtein entitled "Well Construction Report," 7-5-39. WELL DIAGRAM In this column indicate the kind In this column state the kind of Use a red line to show casing Record of of casing, liner, shoe and other formations penetrated, their thickness in FINAL or liner pipe. Use black for drill accessories used. feet and if water bearing. Pumping test or borehoue. Diameter Inches 23'-Standard Steel Casing Depth 2 3 4 5 6 8 10 12 14 16 18 Duration of test Hours. 25Depth of pump in well. Ft. **50** Standing water-level (from surface) Fr. 50 Zt. of water - NE L = 72 deep. Water-level when pumping Ft. Same Water. End of test. Clear. 100 Cloudy_____ Turbid_____ Was the well sterilized? 150To which laboratory was sample no Sample sent 200 Was the well sealed on completion? 400 How high did you leave the casing-pipe above gradel. 800 Well was completed 1200 Draw the diagram to show the right half only