

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39. Accuracy is essential.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of
FINAL
Pumping test

shoe 45 ft of
standard 6 in casing
Cement Platform.

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16		
		25
		45 ft
		50
		65 depth.
		75
		100
		150
		200
		400
		800
		1200

5 ft of top soil.
40 ft of gravel and
quick sand.

25 ft of Blue shale

Duration of test
Hours..... 4 hrs.

Pumping rate
G.P.M..... 8 gal

Depth of pump in
well. Ft..... 30 ft.

Standing water-level
(from surface)
Ft..... 24 ft.

Water-level when
pumping Ft..... 24 ft.

Water. End of test.
Clear.....
Cloudy.....
Turbid.....

Was the well sterilized?
Yes No.....

To which laboratory was sample
sent? state
Date Oct 27 1943

Was the well sealed on comple-
tion?
Yes No.....

How high did you leave the
casing-pipe above grade?
18 inches

Well was completed
Date Aug 21 / 43

Well Constructor
E. S. Waters
Signature

Draw the diagram to show the full diameter and right section of well only.