

WELL LOG and REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.

70 ft.
5 inch standard shoe Pipe

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
		25
		50
		70
		75
		90
		100
		150
		200
		400
		800
		1200

Draw the diagram to show the right half only

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Seventy ft of top soil

50 ft of gravel & shale.

10 ft Blue shale.

Depth 90 ft.

Record of FINAL Pumping test

Duration of test
Hours 4 hrs

Pumping rate
G.P.M. 10 gal

Depth of pump in well. Ft. 25 ft.

Standing water-level (from surface)
Ft. 15

Water-level when pumping Ft. 15

Water. End of test.
Clear
Cloudy _____
Turbid _____

Was the well sterilized?
Yes No _____

To which laboratory was sample sent?
State
Date 8/21-42

Was the well sealed on completion?
Yes No _____
By completion

How high did you leave the casing-pipe above grade?
on the Pit as this is a Pressure system

Well was completed
Date Aug 22 1942

Well Driller
E. S. Waters
Signature