WELL LOG and REPORT

For method of making report, refer to	bulletin entitled "Well Constru	etion R	eport," 7-5-39. Accuracy is essential.	
In this column indicate the kind of casing, liner, shoe and other accessories used.	WELL DIAGRAM Use a red line to show or liner pipe. Use black fo or borehole.	casing r drill	In this column state the kind of formations penetrated, their thickness in feet and if water bearing.	Record of FINAL Pumping test
53 ft of Black Standard Steel 5" Casing	Inches Diameter 2 3 4 5 6 8 10121416	Depth	Heavy black	Duration of test & Res
1-5" Cast Steel drive.	The way of the way to the control of	25	Loose Rock	Pumping rate G.P.M. est - 6 gal
- Case	e documente periode de la company de la comp	50	White Sand	well. Ft. 55
65'dup-			Rock.	Standing water-level (from surface) Ft25
		75		Water-level when pumping Ft. QQ
		100		Water. End of test. Clear Clears Cloudy Turbid
	: 	150		Was the well sterilized? YesYesNo
	· · · · · · · · · · · · · · · · · · ·	200		To which laboratory was sample sent? Jo Malican Date by ourses
	·	400	•	Was the well sealed on completion? Yes Yes No.
		800		How high did you leave the casing-pipe above grade?
	: :			Well was completed Date 11-7-44
807-2	Draw the diagram to show full diameter and right section	the on of	•	Well Constructor H_W_Sartelo