

WELL LOG and REPORT

For method of making report, refer to bulletin entitled "Well Construction Report," 7-5-39. Accuracy is essential.

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of FINAL Pumping test

45' of 5" black Standard Steel casing
1- 5" cast steel drive shoe

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16		
		25
		50
		75
		100
		150
		200
		400
		800
		1200

Soil black and heavy loose rock

White Sand Rock.

65 ft deep.

Duration of test Hours 8 hrs

Pumping rate G.P.M. est 7 gal

Depth of pump in well. Ft. unknown
He installed own pump later -

Standing water-level (from surface) 30 ft of water

Water-level when pumping Ft. est same

Water. End of test. Clear Clear
Cloudy _____
Turbid _____

Was the well sterilized?
Yes Yes No _____

To which laboratory was sample sent?
Madison - To
Date he sent later by owner when he got his pump in.

Was the well sealed on completion?
Yes Yes No _____

How high did you leave the casing-pipe above grade?
16 inches

Well was completed Date 10-11-44

Well Constructor H. W. Bartels
Signature

Draw the diagram to show the full diameter and right section of well only.