(1) AND and REPORT

	2. 1. 1. 1.		
In this column indicate the kind of casing, liner, shoe and other accessories used.	WELL DIAGRAM Use a red line to show c or liner pipe. Use black drill or borehole.	In this column state the kind of formations penetrated, their thickness in feet and if water bearing.	Record of FINAL Pumping test
Std. Wt. pipe Well prillers	Inches Diameter 2 3 4 5 6 8 10 12 14 16 18	Depth Sandy Soil	Duration of test
		25 grave/	Pumping rate G.P.M.
F,S,Shue		50 S. Stone	Depth of pump in well. Ft
		401	Standing water-level (from surface) Ft.
		75	Water-level when pumping Ft
•		80 11	Water End of test
		100	Clear Cloudy Turbid
		150	Was the well sterilized? Yes No
		200	To which laboratory was sample sent? Date 2-2-3-1941
			Was the well sealed o completion? Yes No
		400	
			How high did you leave th casing-pipe above grade?
		800	Well was completed Date 2-23-1941
936-2	Draw the diagram to show right half only	1200 the	Well Driller Carl Mulliam Signature
100-~			