

WELL LOG and REPORT

In this column indicate the kind of casing, liner, shoe and other accessories used.

WELL DIAGRAM
Use a red line to show casing or liner pipe. Use black for drill or borehole.

In this column state the kind of formations penetrated, their thickness in feet and if water bearing.

Record of **FINAL** Pumping test

65' of
Stan
Blk
casing

Inches Diameter		Depth
2 3 4 5 6 8 10 12 14 16 18		
		25
		50
		75
		100
		150
		200
		400
		800
		1200

Sand
and
gravel

water + gravel
white
Sand Rock

DEPTH OF WELL 83'

Duration of test
Hours -----

Pumping rate
G.P.M. -----

Depth of pump in
well. Ft. -----

Standing water-level
(from surface)
Ft. -----

Water-level when
pumping Ft. -----

Water. End of test.
Clear -----
Cloudy -----
Turbid -----

Was the well sterilized?
Yes Yes No -----

To which laboratory was
sample sent?
Will send sample
Date by owner as
soon as pump is
installed.

Was the well sealed on
completion?
Yes Yes No -----

also closed with
an adapter
How high did you leave the
casing-pipe above grade?
16 in

Well was completed
Date Sept 25, 1913

Well Driller
H. W. Bartels
Signature

Draw the diagram to show the
right half only