

WELL CONSTRUCTOR'S REPORT TO WISCONSIN STATE BOARD OF HEALTH  
See Instructions on Reverse Side

RECEIVED  
SEP 8 1952  
ENVIRONMENTAL  
SANITATION

- 1. County Crawford { Town Sec 28, 7N, 5W  
Village \_\_\_\_\_  
City \_\_\_\_\_
- 2. Location on Hyway Leo Horseshoe Tavern
- 3. Owner or Agent Al. Russel
- 4. Address Wauzeka Wis
- 5. From well to nearest: Building 6 ft; sewer \_\_\_\_\_ ft; drain \_\_\_\_\_ ft; septic tank \_\_\_\_\_ ft;  
dry well or filter bed \_\_\_\_\_ ft; abandoned well \_\_\_\_\_ ft.
- 6. Well is intended to supply water for: Tavern

7. DRILLHOLE OR EXCAVATION:

Dia. (in.)	From (ft.)	To (ft.)
<u>6</u>	<u>0</u>	<del>22</del> <u>41</u>

10. FORMATIONS:

Kind	Thick-ness (ft.)	Total Depth (ft.)
<u>Top soil and gravel</u>	<u>0</u>	<u>15</u> 15
<u>Hard sand rock</u>	<u>26</u>	<del>41</del> 41

8. CASING AND LINER PIPE OR CURBING:

Dia. (in.)	Kind	From (ft.)	To (ft.)
<u>6</u>	<u>standard cemented in</u>	<u>0</u>	<u>22</u>

9. GROUT:

Kind	From (ft.)	To (ft.)

11. MISCELLANEOUS DATA:

Yield test: 5 Hrs. at 8 GPM.  
 Depth from surface to water: 12 ft.  
 Water-level when pumping: 12 ft.  
 Water sample sent to laboratory at  
Madison on Sept 2, 1952

Construction of the well was completed on Aug 28, 1952  
 The well is terminated 12 inches (above) ~~(below)~~ the permanent grade.  
 Was the well disinfected upon completion?  
 Yes  No \_\_\_\_\_  
 Was the well sealed watertight upon completion?  
 Yes  No \_\_\_\_\_

Signature Joseph Ball  
 Registered Well Driller

Wauzeka Wis  
 Complete Mail Address