

WELL CONSTRUCTOR'S REPORT TO WISCONSIN STATE BOARD OF HEALTH

See Instructions on Reverse Side CR-7-6

RECEIVED JUN 28 1951 SANITARY ENG.

1. County Crawford Town Village Eastman, Wisconsin City

2. Location Eastman, Piers Add., Lot 12 S. W. 1/4 Sec. 18 T 8 N, R 5 E

3. Owner or Agent Village of Eastman, Wisconsin

4. Mail Address Complete address required

5. From well to nearest: Building ft; sewer ft; drain ft; septic tank ft; dry well or filter bed ft; abandoned well ft.

6. Well is intended to supply water for: Village

7. DRILLHOLE:

Table with columns: Dia. (in.), From (ft.), To (ft.) for two different hole sections.

8. CASING AND LINER PIPE OR CURBING:

Table with columns: Dia. (in.), Kind, From (ft.), To (ft.) for two casing sections.

9. GROUT:

Table with columns: Kind, From (ft.), To (ft.) for grout.

11. MISCELLANEOUS DATA:

Yield test: 24 Hrs. at 165 GPM. Depth from surface to water-level: 402 ft. Water-level when pumping: 465 ft. Water sample was sent to the state laboratory at: Madison on May 20, 1951

10. FORMATIONS:

Table with columns: Kind, From (ft.), To (ft.) for geological formations.

Construction of the well was completed on: May 19, 1951

The well is terminated 24 inches above, below the permanent ground surface.

Was the well disinfected upon completion? Yes X No

Was the well sealed watertight upon completion? Yes X No

Signature: [Signature] Registered Well Driller Dubuque, Iowa Box 237 Complete Mail Address

Rec'd No. Ans'd Interpretation

10 ml 10 ml 10 ml 10 ml 10 ml Gas-24 hrs. 48 hrs. Confirm B. Coli Examiner