

Pulled 24' of 6" Galvanized casing, rimmed a 10" hole to 68'.
Put in new 6" steel casing, with neat cement grout.
Cleaned hole and disinfected well.