

WELL CONSTRUCTOR'S REPORT
FORM 3300-15

JUN 16 1977

NOTE

WHITE COPY - DIVISION'S COPY
GREEN COPY - DRILLER'S COPY
YELLOW COPY - OWNER'S COPY

STATE OF WISCONSIN
DEPARTMENT OF NATURAL RESOURCES
Box 450
Madison, Wisconsin 53701

1. COUNTY Crawford CHECK ONE Town Village City NAME Freeman

2. LOCATION - 1/4 Section N. 1/4 Cor. 7 Section 7 Township 10N Range A R 6W
OR - Grid or street no. Street name
3. OWNER AT TIME OF DRILLING Stanley Van Tassel
ADDRESS 250 Grand Canyon Drive
POST OFFICE Madison Wisconsin

AND - If available subdivision name, lot & block no.

4. Distance in feet from well to nearest:
(Record answer in appropriate block)

BUILDING	SANITARY SEWER	FLOOR DRAIN	FOUNDATION DRAIN	WASTE WATER DRAIN
10'	C. I. TILE	C. I. TILE	SEWER CONNECTED INDEPENDENT	C. I. TILE

CLEAR WATER DRAIN	SEPTIC TANK	PRIVY	SEEPAGE PIT	ABSORPTION FIELD	BARN	SILO	ABANDONED WELL	SINK HOLE
C. I. TILE		100'						

OTHER POLLUTION SOURCES (Give description such as dump, quarry, drainage well, stream, pond, lake, etc.)

5. Well is intended to supply water for: Cottage

6. DRILLHOLE						9. FORMATIONS		
Dia. (in.)	From (ft.)	To (ft.)	Dia. (in.)	From (ft.)	To (ft.)	Kind	From (ft.)	To (ft.)
10"	Surface	80'	6"	80'	103	Shale	Surface	60
						Sandstone	60	103

7. CASING, LINER, CURBING, AND SCREEN			
Dia. (in.)	Kind and Weight	From (ft.)	To (ft.)
6"	<u>Black Steel Cast Iron</u> <u>U.S.S. Weight 18.45</u> <u>A-53</u>	Surface	80
<u>per telephone conversation w/ Edwin Meyer 6/16/77</u>			

8. GROUT OR OTHER SEALING MATERIAL		10. TYPE OF DRILLING MACHINE USED	
Kind	From (ft.)	To (ft.)	
<u>Cement</u>	Surface	80	
		Well construction completed on <u>6/6</u> 19 <u>77</u>	

11. MISCELLANEOUS DATA			
Yield test:	<u>10</u>	Hrs. at	<u>15</u> GPM
Depth from surface to normal water level	<u>75</u>	ft.	
Depth to water level when pumping	<u>90</u>	ft.	
Well is terminated <u>12</u> inches <input checked="" type="checkbox"/> above <input type="checkbox"/> below final grade		Well disinfected upon completion <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	
Well sealed watertight upon completion <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No			

Water sample sent to Madison laboratory on: 6/14 1977

Your opinion concerning other pollution hazards, information concerning difficulties encountered, and data relating to nearby wells, screens, seals, type of casing joints, method of finishing the well, amount of cement used in grouting, blasting, sub-surface pumprooms, access pits, etc., should be given on reverse side.

SIGNATURE Edwin W. Meyer Registered Well Driller COMPLETE MAIL ADDRESS New Albin Iowa Box 55

COLIFORM TEST RESULT 1002 GAS - 24 HRS. GAS - 48 HRS. CONFIRMED REMARKS