WELL CONSTRUCTOR'S REPORT W_1_A

1009

WHITE COPY - DIVISION'S COPY

STATE OF WISCONSIN
DEPARTMENT OF NATURAL RESOURCES
Box 450

π οι -0				GREE	N COPY - DR	LLER'S COPY Madison, Wisconsin 53701 WNER'S COPY			
1. COUNT	Y Charles	1.	1.	CHECK Town		NAME	1		
2. LOCATI	ON (Number a	1/0 0	•	<u> </u>		co give subdivision name, lot and blo	ock numbers when availa	ble.)	
3. OWNER	AT TIME OF	RILLING	- A) -						
4. OWNER	'S COMPLETE	MAIL ADD	JYL	orris	/ } ·	100kg			
			- R	1	terr	willo, Mi	d. 154	76a	8
	ce in feet fro enswer in appro		nearest: B		NITARY SEW C. I. TILI	- F P T	TTON DRAID TED INDEPENDENT	C. I.	ER DRAIN TILE
CLEAR WA	TER DRAIN	SEPTIC TAN	11	SEEPAGE PIT	ABSORPTI	ON FIELD BARN SILO AE	SANDONED WELL SIN	K HOLE	
OTHER PO	LUTTON SOL	TDOTE (Cina	00						
OTREK PO	LLOTION SOC	ORCES (GN)	osseription s	uch as dump,	quarry, drain	age well, stream, pond, lake, etc.)			
6. Well is	s intended	to supply	water for:	1	7 40				
7. DRILLH	IOLE				rom	10. FORMATIONS			
Dia. (in.)	From (ft.)	To (ft.)	Dia. (in.)	From (ft.)	To (ft.)	Kind	F	From (ft.)	To (ft.)
10	Surface	60	6	60	120	Claye		orface C	10
						soft she	Castona	10	4-0
8. CASINO Dia. (in.)	G, LINER, CI	URBING, A (ind and Weigh		N From (ft.)	To (ft.)	for deal	2.	40	90
	new	lack	steel	Surface	/	racampa	estone.		/0
6	laini	end	19.18	0	60	sandston	<u> </u>	70	120
<i>,</i>								1	
				<u> </u>	-				
									
9. GROUT	OR OTHER KG	_	MATERIA	 From (ft.)	To (ft.)				
	00			Surface					
cay				0	10	· · · · · · · · · · · · · · · · · · ·			
11 MISC	ELIANIEOUS	<u> </u>	<u> </u>	10	60	Well construction complete			1970
Yield test	LLANEOUS	DAIA	件 Hrs.	at	8 GPM	Well is terminated	2 inches b	bove elow fina	al grade
Depth from surface to normal water level 90 ft.						Well disinfected upon completion Yes 🗀 No			
Depth to water level when pumping 94 ft.						Well sealed watertight upo	on completion	Yes	☐ No
Water sample sent to Madisann						laborato	ory on: 5 - 26	, , ~	1970
Your opin wells, scr	nion concerr	ning other type of c	pollution asing join	hazards, in	l of finishi	concerning difficulties encoing the well, amount of cerse side.	untered, and data ment used in grou	relating to	o nearby ing, sub-
SIGNATURE						COMPLETE MAIL ADDRESS	0 - 0		
	neth C	mara	γ⁄\ Re	gistered W	/ell Driller	R3 B0x84	Wis. !	386	35
				Please	do not w	rite in space below			
COMPORM (TEST RESULT	•	ĮG	AS — 24 HRS.	GA!	- 48 HRS. CONFIRMED	REMARKS		

REMARKS