WELL CONSTRUCTOR'S REPORT TO WISCONSIN STATE BOARD OF HEALTH Well 6 See Instructions on Reverse Side	
1. County Crawford	Village Pravile du Chien 1965
2. Location Section 27 Range 6 W Joseph T7N  Name of street and number of premise or Section, Town and Range numbers	
3. Owner or Agent & Loren Byers Cleasant Will Factory	
4. Mail Address R 7D Crackes du Chien, His.	
5. From well to nearest: Building 50 ft; sewer 50 ft; drain 6 ft; septic tank 65 ft;	
dry well or filter bed_ 25_ft; abandoned well_ 0ft.	
6. Well is intended to supply water for: Cheose Factory 7. DRILLHOLE:    10. FORMATIONS.	
Dia. (in.)   From (ft.)   To (ft.)    Dia. (in.)   From (ft.)   To (ft.)	From   To
K (   1   11   11   11   11   11   11	Kind (it.) (it.)
10 0 41 60	Clay 0 15
	limerbook 15 165
8. CASING AND LINER PIPE OR CURBING:	Sandrock 165 210
Dia. (in.) Kind and Weight From (ft.) To (ft.)	Limerock) 210 460
6" Standard wit 0 41	270 700
	<del></del>
9. GROUT:	
Kind From (ft.) To (ft.)	
Clay 0 15	
Cement 15 41	Construction of the well was completed on:
11. MISCELLANEOUS DATA:	2-20-
Yield test: 5 Hrs. at 20 GPM.	The well is terminatedinches
Depth from surface to water-level: #-00 ft.	above, below [] the permanent ground surface.
Water-level when pumping: 400 ft.	Was the well disinfected upon completion?
	YesX No
Water sample was sent to the state laboratory at:	Was the well sealed watertight upon completion?
Madison on 2-23 1965	YesNo
Signature Mail Address  Signature Mail Address  Please do not write in space below  Complete Mail Address	
Rec'dFEB 2 5 1965 NoNoNoNoNoNoNoNo	10 ml 10 ml 10 ml 10 ml
Ans'd961 I NYW	Gas—24 hrs
Interpretation	48 hrs
·	Confirm
SAFE EACTERIOLOGICALLY	B. Coli
	Examiner