1. COUNTY	CHECK		NAME	P		
2. LOCATION (Number and Street or 1/4 section, a	Town	Village	<u> </u>	ne lot and block numbers	when available.)	
SE /Il of le	29	77	NR	6 W		
3. OWNER AT TIME OF DRULING	A. (2 0	7	0	pri Ton	
	mr.	John	1 Tuch	a)		
4. OWNER'S COMPLETE MAIL ADDRESS	R1 //	Ps	uries a	Luc ORE	تى سى مىم <i>ىرد</i> سى .	821
5. Distance in feet from well to nearest:	BUILDING SAN	NITARY SEW	ER FLOOR DRAIN	FOUNDATION DRA		TER DRAIN
(Record answer in appropriate block)	2 ا/ حرا	I. I. TILI	C. I. TILE SE	WER CONNECTED INDE	PENTENT C. I.	TILE
	20 0		ZO		/ < 6	-
CLEAR WATER DRAIN SEPTIC TANK PRIVY	SEEPAGE PIT	ABSORPTI	ON FIELD BARN	SILO ABANDONIA	WELL SINK HOLE	
		85	•	1		
OTHER POLLUTION SOURCES (Give description	n such as dump,	querry, drain	age well, stream, pon-	d, lake, etc.)	1	
				. <u>. </u>	<u>-</u>	
6. Well is intended to supply water f	or: Z	iler	. 🗢			
7 DRILLHOLE	Vica	uer	10 FORMATION	<u></u>		
7. DRILLHOLE Dia. (in.) From (ft.) To (ft.) Dia. (in.)	.) From (ft.)	To (ft.)	10. FORMATION	nd ind	From (ft.)	To (ft.)
Surface 44 a	1/ -	41	a	0	Surface	
10 30 70 6	70	760	<u> </u>	Kay	301125	20
			0'	D 4.	20	1100
8. CASING, LINER, CURBING, AND SCR	EENI		eme?	1cock		110
Dia. (in.) Kind and Weight	From (ft.)	To (ft.)	sands	Tomas	110	205
new-black	Surface	11	71	_d_		
6 plainende 19.1	8 00	70	Rimes	tone	205	<u>350</u>
4			sands		350	41
			samas	lone-		7-60
j						
		-				
						
	•					
9. GROUT OR OTHER SEALING MATER	IAL	1 .				
Kind	From (ft.)	To (ft.)				
- CD	Surface	20				
lay		20				
Como fit	20	40	 Well construction	on completed on 🖒	S- 4-	19 68
11. MISCELLANEOUS DATA		_			ahove	
Yield test:	s. at	2 GPM	Well is termina	ted 8 inc	hes 🗍 below fir	nal grade
5 d for the form	2	90 ft.	Well disinfected	d upon completion	🔀 Yes	□ No
Depth from surface to normal water lev	vel <u> </u>	70 ft.				
Depth to water level when pumping 395 ft.			Well sealed wa	stertight upon compl	etion Yes	□ No
		7		laboratore on	<i>F</i> - 0	10 / 0
Water sample sent to Madisc	m, d	Cist.		laboratory on:	<u> </u>	1968
Your opinion concerning other pollution		nformation	concerning diffi	culties encountered,	and data relating	to nearby
wells, screens, seals, type of casing	joints, method	l of finish	ing the well, an	nount of cement use	ed in grouting, blas	sting, sub-
surface pumprooms, access pits, etc., s	nouta pe give	en on reve	75e 5106.			
SIGNATURE		·	COMPLETE MAIL	ADDRESS	52916	
a, <u>a</u> n a			R2R-V	ADDRESS 8 4 Boscon low LCONFIRMED		
Denneth Corpron	Registered W	ell Driller	LINDA	OFILOSCO	sell, on	<u> ソ・ </u>
COLIFORM TEST RESULT	Please (GAS — 24 HRS.	do not w	rite in space be 18 48 HRS.	CONFIRMED	REMARKS	
IJMA			_ 			