## WELL CONSTRUCTOR'S REPORT TO WISCONSIN STATE BOARD OF HEALTH See Instructions on Reverse Side

1. County Crawford	Town Deastman
00	City Check one and give name
2. Location Name of street and number of premise or Section, Town and Range numbers	
3. Owner of or Agent - Roundell	at Brothers
4. Mail Address R. 7. D. Eastern & Complete add	tress required
5. From well to nearest: Building \( \mathcal{Q} \) ft; sewer \( \mathcal{Q} \) ft; drain \( \mathcal{Q} \) ft; septic tank \( \mathcal{Q} \) ft;	
dry well or filter bedQft; abandoned well_2Q_ft.	
6. Well is intended to supply water for: farm home	
7. DRILLHOLE:	10. FORMATIONS:
Dia. (in.) From (ft.) To (ft.) Dia. (in.) From (ft.) To (ft.)	Kind From To (it.)
10 0 98 6 98 295	Clay + loose stone 0 20
	Amestonese 20 55
8. CASING AND LINER PIPE OR CURBING:	flinterock 55 90
Dia. (in.) Kind and Weight From (ft.) To (ft.)	white limestane 90 145
a sianaara wi 0 78	sandstone 145295
9. GROUT:	
Kind From (ft.) To (ft.)	OCT 3 0 1959
clay 0 20	ENVIRONMENTAL
Cement 20 98	Construction of the well was completed on:
11. MISCELLANEOUS DATA:	September 30 1959
Yield test:	The well is terminatedinches
Depth from surface to water-level: 2.2.0 ft.	above, below [] the permanent ground surface.
Water-level when pumping:	Was the well disinfected upon completion?
water-level when pumping:	YesX No
Water sample was sent to the state laboratory at:	Was the well sealed watertight upon completion?
nadison on Oct. 2/ 1959	Yes No
Signature Zawalla Company Registered Well Driller Please do not wr	R3 Box 36 Boscokel His Complete Mail Address
Rec'd CCT 2 2 1959 N37750	10 ml 10 ml 10 ml 10 ml
Ans'd	Gas—24 hrs.
InterpretationINCA	48 hrs.
	Comp 1-1 (9-7)
· <del></del>	Confirm
·	B. Coli
·····	Examiner

576