


Well name Citron Valley Test Hole #2
 Town of Haney
 Owner.... Barnum Farm
 Address.. Route 1
 Steuben, WI 54657
 Driller.. Wisconsin Geological & Natural
 Engineer. History Survey

County: Crawford

Completed... 6/22/78
 Field check. WG&NHS-RMP
 Altitude.... 750' ETM
 Use..... Test
 Static w.l..
 Spec. cap...



Quad. Steuben 7 1/2'

Drill Hole						Casing & Liner Pipe or Curbing							
Dia.	from	to	Dia.	from	to	Dia.	Wgt. & Kind	from	to	Dia.	Wgt. & Kind	from	to
4 1/2"	0	33'											

Drilling method: Auger
 Samples from 0 to 33' Rec'd: 6/22/78

Studied by: Mary J. Hartman

Grout	from	to

Issued: 8/23/85

Formations: Surface, Alluvium, Tunnel City Group.

Remarks: *No constructor's report received*

LOG OF WELL:

	Depths	Graphic Section	Rock Type	Color	Grain Size		Miscellaneous Characteristics
					Mode	Range	
Sfc.	0-7		Soil	Black	--	--	Much organic material.
A	7-8		Silt	"	--	--	Trace clay, organic material.
L	8-18		NO SAMPLE,				
L	18-23		Silt	Dk gry bn	--	--	Much black speckling, little dolomitic clay.
L	23-28		"	Dk yl bn	--	--	Same plus trace Fn glauconite.
24'	28-31		"	Dk gry bn	--	--	Same.
T.C.	31-33		Sandstone	Ol yellow	M	Vfn/AC	Subrounded. Little very good calcite and dolomite cement. Much Fn/M glauconite. Trace chert and dolomite pebbles, mafic inclusions.
END OF LOG							

763