# WELL CONSTRUCTOR'S REPORT TO WISCONSIN STATE BOARD OF HEALTH

See Instructions on Reverse Side

RECEIVED Oct 29 1952 ENVIRONMENTAL SANITATION

1. County Crawford { Town X / Village / City } Utica

2. Location N.W.- S.E. ¼ Sec. 36 T. 10 R. 5 W.

3. Owner ~~or Agent~~ Joe Lucey

4. Address Gays Mills, Wisc. Rt 1.

5. From well to nearest: Building 400 ft; sewer ____ ft; drain ____ ft; septic tank ____ ft; dry well or filter bed ____ ft; abandoned well 450 ft.

6. Well is intended to supply water for: Home & Dairy

## 7. DRILLHOLE OR EXCAVATION:

| Dia. (in.) | From (ft.) | To (ft.) |
|---|---|---|
| 10 | 0 | 84 |
| | | |
| | | |
| | | |

## 8. CASING AND LINER PIPE OR CURBING:

| Dia. (in.) | Kind | From (ft.) | To (ft.) |
|---|---|---|---|
| 6 | Standard "ight | | |
| | pipe | 0 | 84 |
| | | | |
| | | | |

## 9. GROUT:

| Kind | From (ft.) | To (ft.) |
|---|---|---|
| Cement Grout | 84 | 0 |
| | | |
| | | |
| | | |
| | | |

## 10. FORMATIONS:

| Kind | Thickness (ft.) | Total Depth (ft.) |
|---|---|---|
| Top soil and clay0 | 0 | 14 |
| Gravel & Clay | 14 | 21 |
| Flint rock & Clay | 21 | 32 |
| Lime Stone | 32 | 74 |
| Sandstone | 74 | 103 |
| Shalestone | 103 | 122 |
| Sandstone | 122 | 147 |
| ShaleStone | 147 | 168 |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |
| | | |

## 11. MISCELLANEOUS DATA:

Yield test: 5 Hrs. at 10 GPM.

Depth from surface to water: 140 ft.

Water-level when pumping: 148 ft.

Water sample sent to laboratory at La Cross on 10-13 1952

Construction of the well was completed on Oct. 4 1952

The well is terminated 12 inches (above) (~~below~~) the permanent grade.

Was the well disinfected upon completion? Yes XXX No ____

Was the well sealed watertight upon completion? Yes XXXX No ____

Signature Alfred C Jacobson
Registered Well Driller

624 East Broadway, Viroqua, Wisc.
Complete Mail Address

CR 984